



Examples of certification and maintenance of DK-VAND certification

Migration test, Tox. assessment and inspection
Inspection


Material 1




Material 2




Material 3 (Alternative material to material 1)



Material 4 (Alternative material to material 1)




Material 5 (Alternative material to material 1)




Examples of certification and maintenance of DK-VAND certification

Migration test, Tox. assessment and inspection
 Inspection


Material A, PE80




Material B, PE80 (Alternative material to material A)



Material C, PE100 (Alternative material to material D)




Material D, PE100 (Alternative material to material C)




Examples of certification and maintenance of DK-VAND certification

Migration test, Tox. assessment and inspection
 Inspection

Material A



Material B (Alternative material to material A)



Examples of certification and maintenance of DK-VAND certification

Migration test, Tox. assessment and inspection
 Inspection

Red text: Irregular production
 Blue text: Alternative material not used over a three-year period

Material A(B), PE100

Initial certification												
Dimension group	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	
1	used	used	used									Initial approval in December 18
2	not in use	not in use	used									Initial approval in December 18
3-4	not in use	used	not in use									Initial approval in December 18

Material B (D), PE100 (Alternative material to material A)

Initial certification												
Dimension group	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	
1	Used	used	used									Initial approval in December 18
2	used	not in use	used									Initial approval in December 18
3-4	not in use	not in use	not in use									Initial approval in December 18

Material C, PE80

Initial certification												
Dimension group	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	
1			used									Initial approval in March 2020
2			used									Initial approval in March 2020


Material D, PE100 RC

Initial certification												
Dimension group	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	
2	used	used	used									Initial approval in December 18
3	used	used	used									Initial approval in december 18


Examples of certification and maintenance of DK-VAND certification

Migration test, Tox. assessment and inspection
 Inspection


Material A, PE100



Material B, PE100 (Alternative material to material A)



Material C, PE100 (Alternative material to material A)



Material D, PE80

